

# WEALDEN IRON

## *Index to Series I*

Volumes are indicated in **bold** type.

Locations in the British Isles are arranged by civil parish, as currently constituted.

- accounts, Robert Knight, carrier's **XIII** 24; **XIV** 11-24  
    Sidney ironworks **IX** 25
- Adams, R. J. **IX** 23; **XII** 8; **XIV** 9; **XV** 11; **XVI** 15
- Africa, East **VIII** 45
- alien ironworkers **IV** 11-14; **XIII** 17; **XVI** 2-11
- Allarde, Nicholas **XVI** 10
- Alman, Peter **XVI** 5
- Almonde, Nicholas **XVI** 10
- analysis, chemical **IV** 3-10
- ancient monuments, scheduled **III** 19; **XI** 9; **XVII** 19
- Androwe, John **XVI** 10
- Ansty *see under* Cuckfield
- anvil **XIII** 3, 5
- Ardingly (West Sussex) **VII** 18; **XII** 13  
    Ardingly Forge **VII** 18; **VIII** 6; **XII** 13  
    Strudgate Furnace **VII** 18; **XII** 13  
    Wakehurst **XIV** 20
- Arnott, Rev. S. **III** 4
- Arundel (West Sussex)  
    Arundel Park **XIV** 3  
    Nanny's Croft **XIV** 3
- Ashbourne Stream, navigation **XI** 14; **XIV** 5
- Ashburnham clock **XVI** 23
- Ashburnham (East Sussex) **X** 21; **XI** 3, 14; **XII** 7; **XIV** 4  
    aliens in **IV** 12  
    Ashburnham (Dallington) Furnace **VIII** 3, 39; **XII** 7; **XVI** 13  
        source of ore **XI** 3-4  
    Ashburnham (Upper Forge) **VIII** 5, 40  
    Kitchenham **XIV** 5  
    Kitchenham (Ashburnham Lower) forge **VIII** 5, 41; **XI** 7
- Ashburnham family  
    Ashburnham, John **I** 5  
    Ashburnham, Lord **XVI** 13
- Ashdown Forest **X** 22  
    iron sites **XI** 9; **XV** 9; **XVII** 15
- Ashurst (Kent)  
    Ashurst Forge **VIII** 24, 25  
    Ashurst Furnace **VIII** 24
- Ashurst, D. **I** 9
- Attour, Adrian **XVI** 8
- Auneuil (France) **XVI** 4, 6, 7; **XVII** 3
- Averell, Gilbert **XVI** 4
- Awty, B. **XIII** 17; **XVI** 2; **XVII** 2
- 
- Bakaell, Phillippe **XVI** 9
- Balcombe (West Sussex) **X** 22
- Barcombe (East Sussex) **V** 12
- Barden Furnace and Forge *see under* Bidborough
- Bardown *see under* Ticehurst
- Barham, John **XVI** 6; **XVII** 13
- Barkfold Furnace and Forge *see under* Kirdford
- Barrentyne, Sir William **XVI** 7, 8
- Barton, Peter **XVI** 10
- Bartyn, Nicholas **XVI** 6
- Batemans **I** 27
- bath-house **III** 6
- Batsford bloomerie *see under* Hertsmonceux
- Batsford Furnace *see under* Hertsmonceux
- Battle (East Sussex) **VIII** 42; **IX** 13; **X** 22  
    aliens in **IV** 12  
    Beauport Park **I** 9; **III** 4, 7

Beech Furnace **VIII** 3, 42  
 Park Mill 'furnace' **IX** 13  
 Pepperingeye Farm Bloomery **IX** 13  
 Baude, Peter **X** 9; **XVI** 10  
 Bayham Forge *see under* Lamberhurst  
 Baynowe, Peter **XVI** 4  
 bear **III** 9  
 Beaubec (France) **XVI** 4, 5; **XVII** 2  
 Beauport Park *see under* Battle  
 Beaussault (France) **XVI** 4, 8, 9; **XVII** 2  
 Beauvais (France) **XVI** 6, 7, 10; **XVII** 3  
 Beawshaw, Matthew **XVI** 4  
 Beckley (East Sussex)  
     Beckley (Conster) Furnace and Forge **VIII** 3, 5; **IX** 17; **X** 22;  
         **XVI** 13  
     Burnt House Wood, Ludley Farm **IV** 29  
 Bedgebury (Kent)  
     Bedgebury Furnace **VIII** 4, 42  
 Bedgebury Forge *see under* Goudhurst  
 Bedwin, O. **XIV** 9; **XV** 27; **XVI** 24  
 Beech Furnace *see under* Battle  
 Beeching, Thomas **XVI** 23  
 Beeney, D. **XIV** 6, 8  
 Bekebote, John **XVI** 3  
 Ballatt, Mighell **XVI** 9  
 bell pit **V** 18, 20; **XI** 3; **XIV** 6  
 Belleville, John de **XVI** 9  
 Benhall Forge *see under* Frant  
 Bennardus, William **XVI** 3  
 Benne, John **XVI** 10  
 Bennett, Gilham **XVI** 6  
 Bennett, Richard **XVI** 10  
 Bensells Wood *see under* Herstmonceux  
 Bertyne, Jelett **XVI** 5  
 Beuser, Nicholas **XVI** 10  
 Bewbush Furnace *see under* Crawley  
 Bewl Valley **XIV** 8  
 Bewl Valley Ironworks **I** 7; **II** 10; **V** 8; **XI** 29; **XII** 13  
 Bexhill (East Sussex) **VIII** 43  
     Buckholt Furnace and Forge **VIII** 5, 43  
 Bibleham Forge *see under* Mayfield  
 Bibliographies **III** 20-23  
 Bickley Furnace *see under* Beckley  
 Bidborough (Kent)  
     Barden Forge **XVI** 12  
     Barden Furnace **IV** 15-20; **VIII** 4, 28  
 Biddenden (Kent)  
     Biddenden Hammer Mill **VIII** 6; **IX** 17  
 Bingles Farm Bloomery *see under* Withyham  
 Birchden Forge *see under* Rotherfield  
 Bivelham Forge *see under* Mayfield  
 Blackbrook *see under* Crowborough  
 Blackfold Furnace *see under* Cuckfield  
 Blacklands Bloomery *see under* Forest Row  
 Blackman, Herbert **III** 5  
 Blackwater Green Forge *see under* Crawley  
 blast furnace  
     bear **III** 9  
     bloomery slag in **V** 10  
     chemical reactions in **IV** 8  
     description **IV** 16-17  
     dimensions **IV** 7  
     excavation **I** 4-7; **II** 9; **V** 7-10; **XV** 27-31  
     meaning in documentary references **VI** 7  
 Blewett, Lawrence **XVI** 3  
 bloomery  
     dating of **XV** 3  
     experimental **XIV** 9-10; **XV** 11-15  
     medieval **VII** 4-7  
     problem of **VI** 8-10  
     Saxon **VI** 8

slag in blast furnaces V 10

visited by WIRG III 10-13; IV 24-30; V 13-16; VI 17-22;

VII 10-12; VIII 8-11; IX 2-4; XII 4; XIII 6-14; XIV 5;

XV 3-10; XVI 21; XVII 15

blooms

Roman XIV 2-4

Board of Ordnance *see* Ordnance, Board of

Boding, John XVI 3

bog iron IX 23

Bolney (West Sussex) I 10; X 22

Borde, Thomas XVI 9

Boring Wheel Mill *see under* Maresfield

Bosley, J.J. IV 6

Bosmere Farm *see under* Hadlow Down

Botting, W. IV 29

Bottinge, John XVI 4

Botri, Loyes XVI 5

Bouelles (France) XVI 4, 7, 8, 10; XVII 3, 4

Bough Beech Furnace *see under* Hever

Bourne, Mr XVI 13

Bower Forge *see under* Forest Row

Bowyer, Henry XVII 13

Bowyer, John XVI 10

Boyle, Cardo XVI 7

Boyles Farm *see under* East Grinstead

Brambletye Forge *see under* Forest Row

Brambletye Manor Bloomery *see under* Forest Row

Bramshott (Hampshire) IX 5

‘Standford Furnace and Forge’ IV 4; IX 5

Bream Wood Bloomery *see under* Rotherfield

Brede (East Sussex)

Brede Furnace VIII 3; IX 16; X 22; XVI 13

Breechers Forge *see under* Frant

Brenchley (Kent) IV 15; VII 27; XI 15

Brenchley (Horsmonden or Shirrenden) Furnace VII 27; VIII 4

Brent, Mrs Judith III 9; XI 20

Brightling (East Sussex) IX 11

Glazier’s (Brightling) Forge and Furnace VIII 6; IX 10; X 22;

XVI 12, 13

Socknersh Furnace VIII 13; IX 11; XVII 13

Brisay, E de XVII 15

Brisboye, Gwilliam XVI 7

Bristol, shot carried from XIV 12

Broadfield *see under* Crawley

Broadford Bridge *see under* West Chiltington

Broadhurst Furnace *see under* Burwash

Brodribb, A.G. I 9; II 12; III 4; IV 29

Brokes Wood Pond *see under* Southborough

bronze mortar *see under* ordnance

Brookland Forge *see under* Frant

Brown, G.T. IV 4; XIV 3

Browne family, gunfounders IV 15-19; XI 15-19

Browne, George XI 16

Browne, John XI 15-18

Browns Wood Forge *see under* Frant

Buckett, Vincent XVI 10

Buckholt Furnace and Forge *see under* Bexhill

Bugsell Forge *see under* Salehurst

Bulie, Peter XVI 5

Bullie, Jurdain XVI 8

Bunghurst Furnace *see under* Heathfield

Burchall, M. VI 6

Burdett, William XVI 9

Burdewe, Anthony XVI 7

Burgh Wood (Kitchingham) Forge *see under* Etchingam

Buriton (Hampshire) XVII 15

Burningfold Furnace and Forge *see under* Dunsfold

Burnt House Wood, Ludley Farm *see under* Beckley

Burstow (Surrey) III 12

Burton (West Sussex)

Burton Forge VII 16; VIII 6

Burwash (East Sussex) VIII 36; X 23

aliens in **IV** 12  
 Broadhurst Furnace **VIII** 36  
 Burwash Forge **VIII** 6, 38; **XIV** 10; **XVI** 12, 13  
 graveslab **X** 7  
 Butler, D. **I** 26; **V** 10; **XIV** 2  
 Butler, Mr **XVII** 13  
 Buxted (East Sussex) **VIII** 26; **X** 23; **XVII** 19  
   bloomeries **III** 10-11; **IV** 24; **VI** 8, 21; **VIII** 8; **XV** 10  
   Etchingwood bloomery **VI** 8; **VIII** 8  
   Front Wood bloomery **XV** 6  
   Furnace Wood bloomery **VII** 12  
   Hendall Farm **III** 10  
   Hendall Furnace **VI** 17; **XVII** 8  
   High Hurstwood **XV** 6  
   Howbourne Forge **VIII** 5, 26; **XVII** 19  
   Iron Plat Furnace **VI** 30  
   Little Forge **VIII** 6, 16; **XVII** 19  
   Morphews bloomery **VI** 21  
   Newnham Park, Chillies Farm bloomery **VIII** 8; **XIII** 7; **XV** 12  
   Oldlands Furnace **VI** 28  
   Piping Wood **XIII** 7  
   Shadwell Farm bloomery **III** 11; **VI** 20  
   Spaulines bloomery **VIII** 8  
   Tankards Croft bloomery **III** 11  
   Totease **III** 11  
 Buxted Field Group **IV** 24; **V** 13  
 Byllard, John **XVI** 3  
 Byner, Mr **III** 4, 5  
 Bynnet, William **XVI** 10  
  
 Cacherie, James **XVI** 7  
 Cacthery, Peter **XVI** 7  
 camps, fortified **V** 11  
 cannon *see under* Ordnance  
 Canny (France) **XVI** 7; **XVII** 3  
 Cansiron Forge and Furnace *see under* Hartfield  
 Cansiron, Gt., bloomery *see under* Forest Row  
 Capel (Kent)  
   Tudeley bloomery **XV** 8  
 Carbonnet, John **XVI** 3  
 Carone, Robert **XVI** 9  
 carrier's accounts **XIII** 24; **XIV** 11-24  
 Carrs Wood bloomery *see under* Maresfield  
 Carye, John **XVI** 5  
 casting, gun *see under* Ordnance  
 Catillon (France) **XVI** 4; **XVII** 4  
 Catsfield (East Sussex ) **VIII** 41  
   Potmans Forge **VIII** 41  
 Cattell, C.S. **II** 12; **III** 13  
 Cavie, Thomas **VI** 13  
 Chailey (East Sussex) **X** 23; **XVI** 21  
   bloomeries **XVI** 2  
 Chandler, A. **IV** 4  
 Chandlers Farm bloomery *see under* Hartfield  
 Chapel Farm bloomery *see under* Lenham  
 charcoal  
   industry **XI** 26-29  
   making **IV** 18  
 chemical reactions in blast furnace **IV** 8  
 chemistry of wealden iron industry **IV** 3-10  
 Cherford *see* Kirdford  
 Chiddingfold (Surrey) **VII** 14; **IX** 5  
   Imbhams (Embham) Furnace **VII** 14; **VIII** 4  
   West End Furnace **IX** 5  
 Chiddingly (East Sussex) **VIII** 28; **X** 23; **XVI** 18  
   aliens in **IV** 12  
   Stream Forge **VIII** 6  
   Stream (Chiddingly Lower) Furnace **VIII** 3  
 Chillies Farm (Newnham Park) Bloomery **VIII** 8; **XIII** 7; **XV** 12  
 Chingley Furnace and Forge *see under* Goudhurst  
 Chingley, Manor of **VII** 6

Chithurst Forge *see under* Iping  
 Chittingly Furnace *see under* West Hoathly  
 Churchill & Co **XIII** 24  
 cinder **III** 9; *see also* slag  
 Clachoo, Joachim **XVI** 7  
 Cinderberry Field **IX** 24  
 clay ironstone **V** 1-3  
 Cleere, H. F. **I** 4, 26; **II** 4, 6, 11, 12; **III** 6; **IV** 29; **XIV** 2  
 Clerke, Rowland **XVI** 9  
 Clutton & Co **XIII** 24  
 Clutton, Ralph **XIII** 24  
 Clutton, William **XIII** 24  
 coal **XIII** 21; **XIV** 14, 15, 17, 19-21; *see also* charcoal  
 Cobham (Surrey) ironworks **XIV** 12  
 Cohen, John **XIV** 10  
 coins, Roman **XIV** 14-15  
 coles *see* charcoal *or* coal  
 Colegate (West Sussex)  
     St Leonards ironworks **VII** 17; **VIII** 5  
 Collen, John **XIV** 10  
 Collier, Clement **XVI** 11  
 Collier, Jamis **XVI** 8  
 Collier, John **XVI** 8  
 Collier, Nicholas **XVI** 10  
 Collins, Alexander **XVII** 13  
 Collins, Julianne **XVII** 13  
 Collins, Mr **XVI** 13  
 Collyn, Hugh **XVI** 11  
 Colnbrook Common *see under* Northchapel  
 Combe Wood *see under* Ninfield  
 Combes, D. **XIV** 9  
 Combes, Mrs P. **XII** 4  
 Combridge, J. H. **XVI** 23  
 Compainville (France) **XVI** 7; **XVII** 2  
 Coneyhurst Gill Forge *see under* Ewhurst (Surrey)  
 Conster Furnace *see under* Beckley  
 Coombe Furnace *see under* Rogate  
 Coombeswell bloomery *see under* Haslemere  
 Cotchford Forge *see under* Hartfield  
 Cotting, Peter **XVI** 9  
 Coushopley Furnace *see under* Mayfield  
 Cow Park Bloomery *see under* Hartfield  
 Cowbeech (Cralle) Furnace and Forge *see under* Hertsmonceux  
 Cowden (Kent) **VIII** 23; **IX** 7  
     Cowden (Lower) Furnace **VIII** 4, 20  
     Prinkham Farm Forge **VIII** 23  
     Scarlets Furnace and Forge **VIII** 4; **IX** 7, 23; **XVII** 14  
 Cowfield Wood bloomery *see under* Crowborough  
 Cowford Furnace *see under* Rotherfield  
 Cox Mill Bloomery *see under* Dallington  
 Crabtree Farm *see under* Crowborough  
 Cralle (Cowbeech) Furnace and Forge *see under* Hertsmonceux  
 Cranbrook (Kent) **VIII** 42  
     Little Farningham Farm **XIV** 2, 3  
 Crawley (West Sussex)  
     Bewbush (Ifield) Furnace **VIII** 4, 13  
     Blackwater Green Forge **VIII** 14  
     Broadfield **II** 7; **IV** 25; **V** 14, 15; **VI** 15; **VIII** 47  
     Ifield Mill Forge **VIII** 14  
     Moot Hall **VI** 14-15  
     Tilgate Furnace **VIII** 3  
     Tinsley (Tenchley) Forge **VIII** 6, 14; **XVI** 12; **XVII** 13  
 Crawley Down *see under* Worth  
 Crawley Field Group **IV** 25; **V** 14  
 Crèvecoeur (France) **XVI** 8; **XVII** 4  
 Crooked Wood Bloomery *see under* Rotherfield  
 Crossley, D. W. **I** 7, 9; **II** 10, 12; **V** 8; **VII** 4; **VIII** 2; **IX** 25, 27; **XI** 29; **XII** 7, 10, **XIV** 8  
 Crossville (France) **XVI** 9; **XVII** 4  
 Crowborough (East Sussex) **VIII** 8, 10; **IX** 2; **XIII** 12, 14; **XV** 3; **XVI** 24

Blackbrook **III** 11  
 Cowfield Wood Bloomery **IX** 2  
 Crabtree Farm **XIII** 6  
 Oaky Wood **XIII** 12  
 Palesgate bloomery **IX** 2  
 Rose Hill bloomery **VII** 12  
 Crowborough (Grubsbars) Forge *see under* Withyham  
 Crowborough Warren (Withyham) Furnace *see under* Withyham  
 Crowhurst (East Sussex) **VIII** 10; **XIV** 4  
     Crowhurst Furnace and Forge **VIII** 43  
     Crowhurst Park Bloomery **IX** 3  
     Fore Wood bloomery **VIII** 10  
         bloom **XIV** 4  
     Wicks Coppice **IV** 29  
 Crysson, Tarsell **XVI** 9  
 Cuckfield (West Sussex) **VII** 17; **X** 23; **XV** 10  
     aliens in **IV** 12  
     Ansty **I** 10; **XVI** 22  
     Blackfold Furnace **VI** 23  
     Cuckfield Forge **VII** 18  
     Cuckfield Furnace **VII** 18  
     furnaces **VI** 6-7  
     Holmsted (Gastons Bridge) Forge **VII** 17; **VIII** 5  
     Horsgate Farm and Furnace **VI** 7  
     Pilsty ?Furnace **VI** 6  
 Cuespleat Furnace *see under* Mayfield  
  
 Dallington (East Sussex) **X** 23  
     Cox Mill bloomery **VII** 12  
     Panningridge Furnace **I** 4-7; **X** 10  
 Dallington Furnace *see under* Ashburnham  
 Danehill (East Sussex)  
     Northland Farm bloomeries **XIII** 11  
 Darby, Nowell **XVI** 11  
 Darfold Furnace *see under* Etchingham  
 Darwell (Darvell) Furnace *see under* Mountfield  
 Dawson, Charles **XVI** 23  
 Dean, Forest of **IV** 10  
 Debewe, Peter **XVI** 10  
 De Brisay, E. **XVII** 15  
 Dechyn, William **XVI** 8  
 Dedisham Forge *see under* Rudgwick  
 Dedisham Furnace *see under* Rudgwick  
 Deffere, Philippe **XVI** 9  
 Deford, John **XVI** 6  
 Delyche, Nicholas **XVI** 8  
 denization rolls **XIII** 17-19; **XVI** 2-11  
 Deproune, Thomas **XVI** 6  
 Deproune, Valentyne **XVI** 6  
 Deproune, Vincent **XVI** 3  
 Dewall, Peter **XVI** 6  
 Dewvan, John **XVI** 10  
 Dibble, Mr **XVI** 12  
 Dieppe (France) **XVI** 9; **XVII** 4  
 Dogyn, Adrian **XVI** 7  
 Dogyn, John **XVI** 7  
 Dolard, Francis **XVI** 3  
 Domesday *ferraria* **II** 6; **VII** 1  
 Dooze's Farm bloomery *see under* Wadhurst  
 Dorkling (Surrey)  
     Tilehurst Farm **I** 10  
 Douggen, Nicholas **XVI** 10  
 Dowse, Robert **XVI** 7  
 Dry Hill *see under* Lingfield  
 Duchy of Lancaster mss. **XI** 9  
 Duffourd (Duffen), Gyles **XVI** 7  
 Dundle Forge *see under* Pembury  
 Dunsfold (Surrey) **IX** 6  
     Burningfold Furnace and Forge **VIII** 6; **IX** 6; **XVI** 13  
 Dupre, Marian **XVI** 4  
 Dure, John **XVI** 3

Durrant, Samuel **XIII** 24

Easebourne (West Sussex) **X** 23

East Africa **VIII** 45

East Grinstead (West Sussex) **II** 6; **VII** 1, 19; **VIII** 16; **X** 23;  
**XVI** 20

bloomeries **III** 10

Boyles Farm **XIV** 16

Mill Place Furnace **IV** 27; **VIII** 3, 16

Ridge Hill bloomery **IV** 27

Stone Furnace **IV** 27; **VI** 23; **VII** 19

Whillets Bridge bloomery **VI** 17

East Grinstead Field Group **IV** 26; **V** 16

sites visited by **IV** 27-28

East Hoathly (East Sussex)

bloomeries **IV** 4

East India Co **XIV** 12

East Lynden Furnace *see under* Ticehurst

East Wood (Pippingford) bloomery *see under* Maresfield

Ebernoe (West Sussex)

Ebernoe Furnace **VII** 15; **XVII** 14

Wassell Forge **VII** 16

Edenbridge (Kent)

Haxted Watermill **VIII** 46; **XIII** 19

Ellis, John **XVI** 3

Ellis, William **XVI** 3

Ellyot, John **XVI** 10

Embham *see under* Chiddingfold

Ennever, C. C. **XI** 14; **XIV** 4

Eridge Furnace and Forge *see under* Frant

Eridge Old Park bloomeries *see under* Frant

Etchingam (East Sussex) **XIV** 5

aliens in **IV** 12

Burgh Wood (Kitchingham) Forge **XIV** 5

Darfold Furnace **IX** 18

Etchingam Forge **VIII** 5; **IX** 10

Shoyswell bloomery **II** 5

Etchingwood bloomery *see under* Buxted

Eversfield, Nicholas **XVI** 4

Ewhurst (East Sussex)

Ewhurst Furnace **VI** 4; **VIII** 3; **IX** 16; **XII** 2

Ewhurst (Surrey)

Coneyhurst Gill Forge **VIII** 12; **XVII** 16

Ewood Furnace *see under* Newdigate

Farebrother, G . **XIV** 5

Farrant, John **VI** 12

Fen Place *see under* Turners Hill

Felbridge (Surrey) **XIV** 18-20

Woodcock Hammer (Wire Mill) Forge **VIII** 6, 15; **XIV** 12, 19; **XVI**  
12, 13

Fernhurst (West Sussex) **I** 10; **IV** 3; **X** 23

Fernhurst (North Park) Furnace **VII** 14; **VIII** 4

Verdley Wood (Surney Hatch) Furnace **II** 8, 8a; **IV** 5; **VII** 14

*ferraria*, Domesday **II** 6; **VII** 1

field group reports **IV** 24-30; **V** 13-17

field names **II** 12; **III** 2, 3, 8

Filarète, Antonio Averlino **XII** 10

finery forge **XVI** 15-17; *see also* forge

Flat Farm *see under* Hadlow Down

Fletching (East Sussex) **I** 5; **VIII** 18, 19; **X** 23

bloomery **XIII** 15

Fletching Forge **VIII** 19

Sheffield Forge **VIII** 5

Sheffield Furnace **VIII** 19

aliens at **XVI** 2

Sheffield Park **I** 5

flint, use in bloomery furnace **XVII** 15

Foley, Thomas **XI** 17

Folkstone beds **I** 10; **VII** 8

Footlands bloomery *see under* Sedlescombe

Fore Wood *see under* Crowhurst  
 Forest of Dean **IV** 10  
 Forest Row (East Sussex) **II** 6; **XI** 9  
     bloomeries **V** 13  
     Bower Forge **VIII** 5  
     Brambletye Forge **VI** 24; **XVI** 20-21  
     Brambletye Manor bloomery **VI** 8  
     Great Cansiron (Blacklands) bloomery **II** 11; **III** 10, 12; **IV** 21, 27; **VI** 19; **VII** 2; **XI** 9; **XVI** 14; **XVII** 14  
     Rest Hills (Ryst Wood) **XI** 21  
     Walesbeech bloomery **II** 6; **IV** 27; **VI** 18; **VII** 1-2  
 Forewood Bloomery *see under* Crowhurst  
 forge **XIV** 10  
     finery **XVI** 12  
     hammer-forge **XIV** 10  
     reconstruction **XVI** 15-17  
 Fort Jesus (Mombasa) **VIII** 45  
 fortified camps, wealden **V** 11  
 Framfield (East Sussex) **VII** 20; **VIII** 25, 27; **X** 23; **XI** 9; **XV** 6; **XVII** 7  
     aliens in **IV** 12  
     bloomeries **III** 11; **IV** 25; **V** 13  
     Hempstead Wood bloomery **XV** 6  
     Little Streele **XIII** 9  
     New Place Furnace **VIII** 25  
     Paine's Place 'Furnace' **VII** 20; **XVII** 17  
     Pounsley **XV** 9  
     Pounsley bloomery **VI** 22  
     Pounsley Furnace and ?Forge **III** 9; **VIII** 3, 5, 27; **XI** 9  
     Tickerage Furnace and Forge **VI** 30; **VIII** 5  
 Frankham *see under* Wadhurst  
 Frant (East Sussex) **VII** 22; **VIII** 29, 30, 32, 33, 35; **X** 24; **XI** 6, 7; **XVII** 17  
     Benhall Forge **VII** 22; **VIII** 5  
     Breechers Forge **XI** 6  
     Brookland Forge **VII** 5; **VIII** 35  
     Browns Wood Forge **VII** 22  
     Eridge Forge **VIII** 6  
     Eridge Furnace **VIII** 30  
     Eridge Old Park bloomeries **XIII** 13  
     Henley Lower Furnace **VIII** 32; **XIII** 15  
     Henley Upper Furnace **VIII** 33  
     High Rocks (Hungershall) Forge **XVII** 17  
     Riverhall Furnace and Forge **III** 9; **VIII** 4, 5, 34  
     Saxonbury **V** 12  
     Tollslye Furnace **XI** 7  
     Verredge Forge **VII** 23; **XVII** 13  
 Freman, William **XVI** 4, 5  
 Fremyng, Peter **XVI** 5  
 French ironworkers **XIII** 17; **XVII** 2-5  
 Fresard, Gloudo **XVI** 10  
 Freshfield Forge and ?Furnace *see under* Horsted Keynes  
 Friday Street *see under* Wotton  
 Frith Furnace, Kent *see under* Hawkhurst  
 Frith Furnace, Sussex *see under* Northchapel  
 Front Wood bloomery *see under* Buxted  
 Fuller, John **XVI** 13, 17-20  
 Fuller, Rose **XIII** 24  
 furnace *see* blast furnace *or* bloomery  
 Furnace Bank bloomery *see under* Maresfield  
 Furnace Wood bloomery *see under* Maresfield  
 Furnaces and Forges 1664 **VIII** 2-7  
  
 Gage, Peter **XVI** 9  
 Gage, Sir Edward **XI** 20  
 Gailfontaine (France) **XVI** 7; **XVII** 2  
 Gale, Henry **XVI** 12  
 Gamebere, Jeffery **XVI** 10  
 Ganard, John **XVI** 8  
 Garden Hill *see under* Hartfield  
 Gardymbas, John **XVI** 6  
 Garrett, S. **XVI** 15



Garvis, Piers XVI 10  
 Gastons Bridge Forge *see under* Cuckfield  
 Gatewick Farm *see under* West Chiltington  
 Gavell, John XVI 5  
 Gay Street *see under* West Chiltington  
 geology  
     wealden I 10; III 7  
     western Weald I 10-11  
 Gerrard, Nicholas XVI 4  
 Gerrard, Warner XVI 5  
 Gibson-Hill, J. II 7; III 12; IV 25; VI 14; VIII 50  
 Gillett, Giles XVI 7  
 Gillot, Francis XVI 10  
 Glamorgan (Wales) IX 25  
 Glaziers (Brightling) Forge and Furnace *see under* Brightling  
 Glodd, Giles XVI 9  
 Gloucester Furnace *see under* Lamberhurst  
 Goderd, John XVI 3  
 Goring, J. J. XV 32  
 Gosden Furnace *see under* Lower Beeding  
 Gospel Green *see under* Northchapel  
 Gott, Miss XVI 13  
 Gotter, Nicholas XVI 11  
 Gottere, John XVI 11  
 Goudhurst (Kent) IX 12  
     Bedgebury Forge IX 12  
     Chingley Forge I 7-9; II 9-10; VII 5; XI 29-31; XII 13; XIV 8;  
         XVI 12  
 Gowghtier, Nicholas XVI 10  
 Graunte, Lawrence XVI 7  
 Gravetye Furnace *see under* West Hoathly  
 Great Cansiron *see under* Forest Row  
 Greatham (Hampshire)  
     Weavers Down I 11; IV 3, 4  
 Growte, Nicholas XVI 6  
 Grubsbars Forge *see under* Withyham  
 Gumrie, John XVI 8  
 gunfounders *see under* ordnance  
 guns *see under* ordnance  
 Guntier, John XVI 11  
  
 Habin Forge *see under* Harting  
 Hadlow Down (East Sussex) XIII 10, 13; XV 9  
     Bosmere Farm XIII 10  
     Flat Farm XIII 10  
     bloomeries IV 25  
     Howbourne bloomery VI 21  
     Huggetts Furnace X 9  
     Scocus XIII 13  
 Hambledon (Surrey) I 10  
 Hammer Forge *see under* Westwell  
 hammer-forge *see under* forge  
 Hammersley, G. XI 26  
 Hamsell Furnace *see under* Rotherfield  
 Hanizett, Jakes XVI 3  
 Hany-site, Adrian XVI 3  
 Harby, Peter XVI 3  
 Harrietsham (Kent) IX 21  
     Runhams Farm IX 21  
 Harrison brothers XVI 13  
 Harrison, Reynolde XVI 8  
 Hartfield (East Sussex) IV 11, 24; VIII 20; XI 9; XV 16  
     aliens in IV 12  
     bloomeries III 10; IV 24  
     Cansiron Forge and ?Furnace IV 27; VIII 5, 20  
     Chandlers Farm bloomery III 10; VI 8, 20  
     Cotchford Forge VI 27; XI 9  
     Cow Park bloomery XI 4; XII 3; XIII 2-6; XV 12  
     Garden Hill V 12; VI 19; XV 16-26  
     Hartfield Forge VI 28  
     Harts Lane bloomery VI 20

Holtye III 2  
 Kings Standing Farm bloomery VI 20  
 Millbrook Saxon bloomery XVII 15  
 Newbridge Forge VI 28; XI 10  
 Newbridge Furnace VI 25; XI 9; XII 10  
     aliens at XVI 6  
 Parrock bloomery VI 8, 19  
 Parrock Furnace and Forge VI 26; XI 11; XII 12  
     aliens at XVI 6  
 Paupersdale Wood III 10  
 Pippingford bloomery II 11; III 10; VI 18; XI 9  
 Pippingford Furnace V 7; VI 15; XI 13; XV 10  
 Steel Forge, Pippingford XI 10  
 Strickedridge Gill bloomery II 10; VI 19  
 Tugmore Shaw XI 9  
 Upper Parrock bloomeries VII 11  
 Wick Wood III 10  
 Harting (West Sussex)  
     Rogate (Habin) Forge VII 13  
 Harting (Coombe) Furnace *see under* Rogate  
 Hartley, K. IV 21  
 Harts Lane bloomery *see under* Hartfield  
 Harvy, John XVI 9  
 Harvy, Remy XVI 9  
 Hascombe (Surrey) I 10; V 11  
 Haslemere (Surrey) I 10; V 4; IX 5  
     Coombeswell bloomery IV 4; V 4-7; VII 10  
     Shottermill 'Forge' IX 5  
 Hastings (East Sussex)  
     bloomeries IV 29  
     Hollington III 4  
 Hastings field group IV 29  
 Hatto, Audryan XVI 9  
 Hatto, John XVI 3  
 Hattowe, William XVI 3  
 Haucourt (France) XVI 7; XVII 3  
 Hawkhurst (Kent) IV 15  
     Frith Furnace IX 13  
     Hawkhurst Furnace VIII 4; IX 15  
 Hawksden Forge and Furnace *see under* Mayfield  
 Haxted Watermill *see under* Edenbridge  
 Haxted Watermill XIII 19  
 Heathfield (East Sussex) III 9, 13; VI 13; X 24  
     bloomeries III 12  
     Bungehurst Furnace VII 21  
     Heathfield Furnace VIII 31; XVI 13, 18  
     Newick Wood III 9  
     Tilsmore Wood bloomery VI 22  
 Hedgecourt Furnace *see under* Worth  
 Helys, Anthony XVI 3  
 Hempstead Wood bloomery *see under* Framfield  
 Hemsley, D. II 6; III 6, 7  
 Hendall Farm *see under* Buxted  
 Hendall Furnace *see under* Buxted  
 Henfield (West Sussex) I 10  
 Henley Lower Furnace *see under* Frant  
 Henley Upper Furnace *see under* Frant  
 Herbert, B. K. IV 10, 22, 26, 30; VIII 47; XIII 19  
 Herstmonceux (East Sussex) VII 24; XIV 6, 8; XV 9  
     Batsford bloomeries XVII 16  
     Batsford Furnace VII 24; XIV 8; XV 27-31  
     Benzells Wood XIV 6  
     bloomeries XV 9  
     Cowbeech (Cralle) Furnace and Forge VII 23; VIII 4-5  
 Heth, Nicholas XVI 10  
 Hever (Kent) VII 20; VIII 22  
     Bough Beech Furnace IV 27; VII 20; VIII 22  
 High Hurstwood *see under* Buxted  
 High Rocks (Hungershall) Forge *see under* Frant  
 Historical Metallurgy Society XV 2; XVI 22  
 Hoathly (Lamberhurst) Forge *see under* Lamberhurst

Hodesdale Forge *see under* Mountfield  
 Hodges Wood Bloomery *see under* Rotherfield  
 Hodgkinson, J.S. **XIII** 24; **XIV** 11; **XVI** 11; **XVII** 6  
 Hogge, Ralph **IX** 27; **X** 9  
     ironworks accounts **IX** 25  
 Holbeanwood *see under* Ticehurst  
 Hollingbourne (Kent) **VI** 3, 5  
 Hollingbury Camp (Brighton) **IX** 24  
 Hollington *see under* Hastings  
 Holmes, Gilham **XVI** 6  
 Holmsted (Gastons Bridge) Forge *see under* Cuckfield  
 Holtye *see under* Hartfield  
 Horam (East Sussex) **II** 12  
 Horley (Surrey) **I** 11  
     Thundersfield Castle **I** 11; **IV** 28  
 Horne, E. **VIII** 50  
 Horsebane Hammer Forge *see under* Thursley  
 Horsgate Farm and Furnace *see under* Cuckfield  
 Horsham (West Sussex) **I** 10; **V** 20; **VIII** 12; **X** 24  
     Warnham Furnace **VIII** 4, 12  
 Horsmonden (Kent) **IV** 15  
 Horsmonden Furnace *see under* Brenchley  
 Horsted Keynes (West Sussex) **VIII** 17; **X** 24  
     Freshfield Forge and ?Furnace **VIII** 5, 17; **XIII** 14  
     Horsted Keynes Furnace **VII** 19; **VIII** 3  
 Howbourne bloomery *see under* Hadlow Down  
 Howbourne Forge *see under* Buxted  
 Howell, John **XVI** 11  
 Huggetts Furnace *see under* Hadlow Down  
 Hungershall Forge *see under* Frant  
 Hurst Green (East Sussex) **II** 6  
     Iridge bloomery **IX** 3  
     Iridge Furnace **II** 6; **IX** 14  
 Hurstpierpoint (West Sussex) **VI** 5  
 Hythe Beds **I** 10

Ifield *see under* Crawley  
 Ifield Mill Forge *see under* Crawley  
 Ightham (Kent) **VI** 3  
 Imbhams Furnace *see under* Chiddingfold  
 immigrants **XVI** 2-11, *see also* aliens  
 Inholmes Copse Furnace *see under* Stedham  
 inquisitions **XVII** 12-14  
 Iping (West Sussex)  
     aliens in **IV** 12  
     Chithurst Forge **VII** 13; **X** 23  
 Iridge bloomery *see under* Hurst Green  
 Iridge Furnace *see under* Hurst Green  
 iron industry, historical records of **XVII** 12-14  
     western Weald **I** 10  
     and fortified camps **V** 11  
 iron ore *see under* ore  
 iron pan **IX** 23  
 iron Plat Furnace *see under* Buxted  
 iron sites, scheduling of **XVII** 19  
 iron workers **XVI** 2-11; **XVII** 2-5  
 ironmasters, wealden **XV** 32-33  
 ironworkers **XVI** 2-11; **XVII** 2-5  
     French **XIII** 17; **XVII** 2-5  
     wages **IV** 17  
 iron-working settlement, Garden Hill **XV** 16-26  
 ironworks, 15th Century description of **XII** 10  
     Romano-British **XV** 23  
 Isfield (East Sussex) **V** 12  
 Isted family **XVI** 4

Jack, Sybil M. **XVII** 12  
 Jeffrey, Bartholomew **I** 4  
 Jenner family **VI** 6-7  
 Johnson, Cornelys **XVI** 10  
 Johnson, Jeremiah **XVI** 12

Johnson, John X 9

Joly, John XVI 10

Jonner, John XVI 6

Kenyon G.H I 10; II 8; V 11

Kings Standing Farm bloomery *see under* Hartfield

Kirdford I 10; VII 15, 16, 17; X 25

Barkfold Furnace and Forge VII 17

Roundwick Furnace VII 16

Kirsop, B. III 12

Kitchenham (Ashburnham Lower) Forge *see under* Ashburnham

Knepp Furnace *see under* Shipley

Knight, John XVII 14

Knight, Robert XIII 24; XIV 11

Kydville, Cardo XVI 4

Kynnery, Nicholas XVI 5

Laby, John XVI 3

Labye, Richard XVI 10

Lamberhurst (Kent) I 7; II 10; X 25; XI 7

Bayham Forge VII 25; VIII 6

Gloucester (Lamberhurst) Furnace VII 26; VIII 6

Hoathly (Lamberhurst) Forge VII 26; VIII 6

Old Forge Farm I 7

Lambert Francis XVI 8

Lambert, John XVI 6

Lambert, Michael XVI 10

Lambert, Peter XVI 5

Lamye, Izambard XVI 9

Lancaster, Duchy of XI 9

Langleys Furnace and Forge *see under* Maresfield

Langleys, John XVI 7

Larbye, Morys XVI 5

Lavender, John XIV 14; XVI 9

Lawhen, Peter XVI 5

Lawrens, Gyles XVI 9

Layne, Thomas XVI 5

leat, Brambletye Forge XVI 21

Lebon, M. C. XIV 2

Lee, R. XVII 18

Leigh (Surrey)

Leigh Hammer Forge VIII 13

Lenarde, James XVI 6

Lenham (Kent) V 12; VI 3, 5

Chapel Farm bloomery, Lenham Heath VII 8; IX 22

Lewes (East Sussex) X 6

Lewisham (London) XIV 16

Lickfold *see under* Lodsworth

Limney bloomery *see under* Rotherfield

Linch (West Sussex) X 26

Linchmere (West Sussex) IX 5; X 25

Pophole Forge and ?Furnace VIII 6; IX 5

Shulbrede Priory IV 3

Lindfield (West Sussex) X 26

Lingfield (Surrey)

Dry Hill V 11

Raby's Farm XIV 11

Upper Stonehurst bloomeries IV 28

Wilderwick XIV 14

Little Farningham Farm *see under* Cranbrook

Little Forge *see under* Buxted

Little Streele *see under* Framfield

Lodsworth (West Sussex)

Lickfold I 10

Lower Beeding (West Sussex) VII 17

Gosden Furnace VII 17

Lower, M.A. III 4; VIII 2; X 2

Lower Marshalls Forge *see under* Maresfield

Loye, Marten XVI 11

Lucas, Mawdyn XVI 5

Lullingstone (Kent) VI 3, 5

Lunsford, master XVI 6  
 Lurgashall (West Sussex)  
     'bloomey' VII 10  
 Lygon, Robert XVI 7  
 Lyle, Peter de XVI 3  
 Lyonarde, John XVI 9  
 Lynch X 26  
  
 magnetometer survey V 4-7  
 Major, J. K. XV 31  
 Makecowbull, John XVI 9  
 Manton, James XVI 111  
 Manwaring Baines, John XVII 9  
 Marchaunt, Hugh XVI 10  
 Maresfield (East Sussex) VIII 17; X 26; XVII 8  
     Boring Wheel Mill VI 26; XVII 8  
     CarrsWood bloomey XVII 8  
     East Wood bloomey VII 11  
     Furnace Bank bloomey III 10; IX 19; XVII 8  
     iron sites XVII 8  
     Langleys (Lower Marshalls) Furnace and Forge VI 24; XVII 8  
     Maresfield Forge VIII 6-21; IX 19-21; XIII 24, 25; XVI 12, 13  
     Maresfield Furnace VIII 22; IX 19; XVII 8  
     Maresfield Powder Mills VIII 21; IX 19-21  
     Old Forge (Marshalls) Furnace VI 26; XVII 8  
     Oldlands bloomey VI 20; X 3-4; XVII 8  
     Reedings Farm bloomey VII 11; XVI 8  
     Streeters Farm bloomey XVII 8  
     Stumblett's Furnace VIII 17; XVII 8  
     Tinkers Wood bloomey XVII 8  
 Margary, I. D. II 11; III 2  
 Margo, John XVI 6, 7  
 Marian, Richard XVI 9  
 Marinus IV 21  
 Mark Cross *see under* Rotherfield  
 Markly (Rushlake Green) Furnace *see under* Warbleton  
 Marl V 18  
 Marshalls Furnace, Lower *see under* Maresfield  
 Marshfield Furnace *see under* Maresfield  
 Masters & Raby, Messrs XIII 25  
 Mayfield (East Sussex) II 5; III 9, 13; VIII 10, 30, 33, 35, 37;  
     X 26; XI 5; XV 10  
     Bivelham (Bibleham) Forge VIII 6, 37; XVI 12, 13  
     bloomeies III 11; V 13  
     Coushopley (Cuespleat) Furnace VIII 3, 33  
     Hawkesden Forge VIII 6, 35; XVI 12, 13  
     Hawkesden Furnace Mill IX 15  
     Mayfield Furnace VI 31; VIII 3; XVII 17  
     Moat Mill Forge VIII 30  
     Old Mill Furnace VIII 30  
     Smithfield Shaw bloomey VI 22  
     Witherenden II 5; VIII 37  
     Woolbridge (water-powered bloomey) Furnace or Forge XI 5  
 Mayfield cannon XIII 22, 23  
 Maynards Gate bloomey *see under* Rotherfield  
 Maynards Gate Furnace *see under* Rotherfield  
 McCarthy, P. XIII 22  
 medieval iron-working sites VI 8-10  
 Mergeyes, James de XVI 7  
 Melhill Forge *see under* Pembury  
 Meryall, Henry XVI 8  
 Mesans, William XVI 3  
 Mettall, Philpott XVI 7  
 Michell, Nicholas XVI 9  
 Mighell, Nicholas XVI 8  
 Miles, A. VII 8  
 Mill Place Furnace *see under* East Grinstead  
 Millbrook Saxon bloomey *see under* Hartfield  
 mine *see ore*  
 Minepit Wood bloomeies *see under* Rotherfield  
 mines, iron XVI 17

mining **V** 18, 20; **XI** 3  
 Mitchell Park Farm Forge *see under* Northchapel  
 Mitell, Jermain **XVI** 9  
 Moat Mill Forge *see under* Mayfield  
 Mocomble, Jelett **XVI** 5  
 Money, J. H. **II** 11, 12; **V** 19; **XV** 16  
 Moonlye, Rowland **XVI** 8  
 Moonsell, David de **XVI** 3  
 Moot Hall *see under* Crawley  
 Morell, Remy **XVI** 2, 5  
 Morrell, Jamys **XVI** 4  
 Morrell John **XVI** 8  
 Morphews Bloomery *see under* Buxted  
 mortar *see under* ordnance  
 Mountfield (East Sussex) **VII** 27; **IX** 14; **XVII** 9  
 Darwell (Darvell) Furnace and Forge **VII** 27; **VIII** 3; **IX** 18; **XVI** 13;  
     **XVII** 9-12  
     Hodesdale Forge **VIII** 5; **IX** 14  
     Mountfield Furnace and Forge **IX** 14  
 Mousehall *see under* Wadhurst  
 Museum of Wealden Iron **XIII** 19-21  
 Myschewe, John **XVI** 5  
 Myttell, Anthony **XVI** 9

Nannys Croft *see under* Arundel  
 Netherfield (East Sussex) **I** 4  
     aliens in Netherfield Hundred **IV** 12.13  
 Neufchâtel en Bray (France) **XVI** 4, 7, 9, 10; **XVII** 2  
 New Place Furnace *see under* Framfield  
 Newbridge Furnace and Forge *see under* Hartfield  
 Newdigate (Surrey) **VI** 3; **VIII** 13  
     Ewood Furnace **VIII** 13  
 Newhaven, ordnance shipped from **VI** 12  
 Newick (East Sussex) **X** 26  
 Newick Wood *see under* Heathfield  
 Newnham Park (Chillies Farm) bloomery *see under* Buxted  
 Nicoll, Benett **XVI** 10  
 Ninfield (East Sussex)  
     Combe Wood **XI** 3; **XIV** 4  
     Standard Hill Farm **XIV** 4  
 Norfolk, Duke of **XVI** 2, 5, 8  
 Northchapel (West Sussex) **VII** 15, 16; **X** 26  
     Colnbrook (?Colehook) Common **I** 10  
     Frith Furnace **VII** 15; **VIII** 3; **IX** 13  
     Gospel Green **I** 11  
     Mitchell Park Farm Forge **VII** 16  
 Northiam (East Sussex) **IX** 16; **XII** 2  
     Northiam Furnace **VIII** 3; **XII** 2  
 North Park Furnace *see under* Fernhurst  
 Northland Farm bloomeries *see under* Danehill  
 Nufflyd, Gilham **XVI** 6  
 Nutfield (Surrey) **III** 12

Oaky Wood *see under* Crowborough  
 Old Forge Farm *see under* Lamberhurst  
 Old Forge (Marshalls) Furnace *see under* Maresfield  
 Old Mill Furnace *see under* Mayfield  
 Oldlands bloomery *see under* Maresfield  
 Oldlands Furnace *see under* Buxted  
 ordnance  
     boring **XV** 31; **XVII** 18  
     bronze **XIV** 12; **XVII** 6  
         casting of **XI** 15-20  
         carriage of **XIV** 14-20  
         casting **IV** 15  
         furnace reconstruction **XII** 8  
     in East Africa **VIII** 45  
     lying at Eridge **X** 8  
     Mayfield falcon **XIII** 22-23  
     mortar, bronze **XIV** 12; **XVII** 6  
     shipment of **VI** 12

wealden **XVII** 6  
 Ordnance, Board of **XIII** 24  
     purchase of ordnance and shot **XIV** 11  
 ore **IV** 15, 17-18; **V** 1-3; **XIV** 4; **XVI** 18-20; **XVII** 18  
     digging **V** 18, 20; **XI** 3, 20-26; **XIV** 4, 6-7  
     pitty **XVI** 18-19  
     Siderite **V** 1-3  
     sources for bloomeries **XI** 3  
 Orznash *see under* Rotherfield  
 Ovenden, P.J. **I** 11; **II** 8; **IV** 3, 29; **V** 4  
 Oyddes, Michael **XVI** 10  
  
 Paine's Place Furnace *see under* Framfield  
 Palesgate bloomery *see under* Crowborough  
 Pallingham Furnace *see under* Wisborough Green  
 Panningridge Furnace *see under* Dallington  
 pantograph **IV** 22  
 Park Mill 'Furnace' *see under* Battle  
 Parmenty, James **XVI** 3  
 Parrock bloomery *see under* Hartfield  
 Parrock Furnace and Forge *see under* Hartfield  
 Parsons, J.L. **VIII** 2  
 Paryse, James à **XVI** 11  
 Paupersdale Wood *see under* Hartfield  
 Peckham family **II** 6  
 Pelham, Mr **XVI** 6  
 Pembury (Kent) **VII** 25; **XI** 6  
     Dundle Forge **VII** 25  
     Melhill Forge **XI** 6  
 Penhurst (East Sussex) **X** 26; **XII** 7  
     Penhurst Furnace **XI** 8  
 Pepperingeye Farm bloomery *see under* Battle  
 Prygo, John **XVI** 4  
 Pettitt, J. **II** 12; **III** 3, 8, 14 (poem); **IV** 11; **V** 12; **VI** 3, 13; **VII** 1;  
     **IX** 19; **XIV** 10; **XVII** 8  
 Petworth (West Sussex) **I** 10; **X** 27  
 Pexwell, William **XVI** 11  
 Philpott, John **XVI** 10  
 Pilsty ?Furnace *see under* Cuckfield  
 Piper's Copse *see under* Northchapel  
 Piping Wood *see under* Buxted  
 Pippingford bloomery *see under* Hartfield  
 Pippingford Furnace *see under* Hartfield  
 Pippingford Steel Forge *see under* Hartfield  
 pitty ore *see ore, pitty*  
 Plaistow (West Sussex)  
     Shillinglee Furnace **VII** 15  
 Plumpton (East Sussex) **VI** 4  
 Polen, Charles **XVI** 6  
 Pophole Forge & ?Furnace *see under* Linchmere  
 Postern Forge *see under* Tonbridge  
 pot bellows **XIV** 3  
 Potmans Forge *see under* Catsfield  
 Potte, George **XVI** 11  
 Potter, Thomas **XVI** 10  
 pottery **IV** 21  
 Pounsley bloomery *see under* Framfield  
 Pounsley Furnace *see under* Framfield  
 Poutsse, Lawrence **XVI** 11  
 Predome, Marian **XVI** 8  
 Prinkham Farm Forge *see under* Cowden  
 publications by WIRG members **II** 12  
 Pullen, Bartyne **XVI** 8  
 Pullen, Charles **XVI** 8  
 Pylas, Robert **XVI** 10  
 Pyllar, Quintin **XVI** 5  
 Pynson, William **XVI** 10  
 Pynyon, Everode **XVI** 6  
 Pynyon, John **XVI** 4  
  
 questionnaire, site **I** 23

Raby, Alexander XIV 12, 15; XVI 13  
 Raby & Co XIII 24  
 Raby, Edward XIV 11-12; XVII 6  
 Raby & Rogers, Messrs XIV 20, 22-23  
 Raby's Farm *see under* Lingfield  
 Racreffo, Jakes XVI 3  
 Rats Castle Forge *see under* Tonbridge  
 Ravenell, George XVI 8  
 Rawe, Simon XVI 9  
 Rawsner, Lewes XVI 6  
 Ray, John, account of ironmaking X 18  
 Reedings Farm bloomery *see under* Maresfield  
 relationship with other bodies I 26  
 Relfe, William I 4  
 Renby Grange *see under* Rotherfield  
 Rest Hills (Ryst Wood) *see under* Forest Row  
 Richard, Nicholas XVI 9  
 Ridge Hill bloomery *see under* East Grinstead  
 Ringmer (East Sussex) V 12  
 Riverhall Furnace and Forge *see under* Frant  
 Rivers, Henry XIII 25  
 Robertsbridge Abbey Forge *see under* Salehurst  
 Robertsbridge Abbey Furnace *see under* Salehurst  
 Robbery, John XVI 8  
 Robey, John XVI 9  
 Robynett, John XVI 4  
 Rock, James III 4  
 Rocketh, Gillam XVI 8  
 Rockley (Yorkshire) I 5  
 Roffey bloomery *see under* Rusper  
 Rogate (West Sussex)  
     (Harting) Coombe Furnace VII 13  
 Rogate (Habin) Forge *see under* Harting  
 Rogers, Messrs Raby & XIV 20, 22-23  
 Roman  
     coin XVI 14  
     road V 12; XVII 9  
     settlement, (Garden Hill) XV 16-26  
 Rosay (France) XVI 9; XVII 3  
 Rose Hill Bloomery *see under* Crowborough  
 Rossell, Myntan XVI 11  
 Rother (Eastern), river  
     bloomeries in basin of III 13  
 Rotherfield (East Sussex) III 13; VII 21; VIII 27, 28, 29, 30; X 27  
     Birchden Forge VIII 6, 27  
     Bream Wood bloomery IX 2  
     Cowford Furnace VI 30  
     Crooked Wood bloomery IX 3  
     Hamsell Furnace IV 15; VIII 28; XVI 13  
     Hodges Wood bloomery VIII 10; XV 3  
     Limney bloomery III 11; VI 22  
     Mark Cross XIII 9  
     Maynards Gate bloomery XII 4-7  
     Maynards Gate Furnace VII 21; VIII 3; XII 4; XVI 24; XVII 8,  
         18  
     Minepit Wood bloomeries I 4; II 12; V 9; VII 4  
     Orznash II 12  
     Renby Grange IX 2, 3; XIII 14  
     Rough Wood Gill bloomery IX 2  
     Walnut Tree Field bloomery IX 2  
 Roundwick (Roundwyck) Furnace *see under* Kirdford  
 Roville (France) XVI 10; XVII 4  
 Rowe, Robert XVI 10  
 Rowfant *see under* Worth  
 Rowfant Forg *see under* Worth  
 Rowfant Supra Forge *see under* Worth  
 Roys, William XVI 11  
 Rudgwick (West Sussex) VIII 12; IX 6  
     Dedisham Forge IX 6  
     Dedisham Furnace VIII 12



Runhams Farm *see under* Harrietsham  
 Rushlake Green (Markly) Furnace *see under* Warbleton  
 Rushlake Green bloomery *see under* Warbleton  
 Rusper (West Sussex)  
     Roffey bloomery IX 2  
 Russel, Abre XVI 4  
 Russell, Clement XVI 10  
 Russell, Gillet XVI 3  
 Russell, Obery XVI 3  
 Russell, Onyen XVI 3  
 Russell, Peter XVI 3  
 Rutland, My Lady of XVI 9  
 Ryst Wood (Rest Hills) *see under* Forest Row  
  
 Sackville, Sir Richard VI 3; XI 20  
 safety in fieldwork VI 2  
 St Leonards Forest X 27  
 St Leonards Ironworks *see under* Colegate  
 Salehurst (East Sussex) IX 3, 12, 14; X 27  
     aliens in IV 12  
     Bugsell Forge VIII 5; IX 12; XII 3  
     Robertsbridge Abbey Forge I 4; VIII 6; IX 12, 25; XII 3; XVI 13  
     Robertsbridge Abbey Furnace I 4; VIII 3; IX 15, 25; XIII 24;  
         XVI 13  
 Salzman, L.F VII 1-2  
 Sampson, John XVI 11  
 Sandgate Beds I 10  
 Sandyden Gill bloomery *see under* Wadhurst  
 Saville, R. XVI 17  
 Saxon bloomeries VI 8  
 Saxon ironworking XVII 15  
 Saxonbury *see under* Frant  
 Scarlets Furnace and Forge *see under* Cowden  
 scheduling of sites as Ancient Monuments III 19; XI 9; XVII 19  
 Schubert, H.R. II 6; IV 3, 4, 11  
 Scocus *see under* Hadlow Down  
 Scott, A. III 6; IV 29  
 Scott, B. VII 9  
 Scottish History Society IV 15  
 Scrag Oak (Snape) Furnace *see under* Wadhurst  
 Sedlescombe (East Sussex) IX 3; X 27  
     Footlands bloomeries IX 3  
 Sewill, Mrs Ruth VI 10; XV 2  
 Shadwell Farm bloomery *see under* Buxted  
 Shalford (Surrey) VI 3  
 Shamelett, Gyles XVI 8  
 Sheffield Forge *see under* Fletching  
 Sheffield Furnace *see under* Fletching  
 Sheffield Park *see under* Fletching  
 Shelley, Mrs Jean VI 10  
 shells, carriage of XIV 20  
 Shermun, John XVI 4  
 Shillinglee Furnace *see under* Plaistow  
 Shingley (Chingley) Forge *see under* Goudhurst  
 Shipley (West Sussex) IX 6  
     Knepp Furnace IX 6; X 27  
     Shipley Forge IX 6; X 27  
 Shivaller, Francis XVI 10  
 Shoell, Reynolde XVI 10  
 Shoreham (West Sussex) IX 22  
     Slonk Hill IX 22  
 shot  
     carried from Bristol XIV 12  
     purchased by the Board of Ordnance XIV 12  
 Shottermill IX 5  
 Shottermill 'Forge' *see under* Haslemere  
 Showen, Nicholas XVI 10  
 Shoyswell Bloomery *see under* Etchingham  
 Shulebrede Priory *see under* Linchmere  
 Siderite *see under* ore  
 Sidney Ironworks Accounts IX 25

Sidney, Sir Henry **IX** 25  
 Sidney, Sir William **I** 4; **XVI** 7  
 site questionnaire **I** 23  
 sites, scheduling of **III** 19; **XI** 9  
 sites, serial numbers **I** 13-18  
 sites visited by WIRG **VI** 17-31; **VII** 10-27; **VIII** 8-44; **IX** 2-18;  
     **XI** 6-8; **XIII** 6-15; **XIV** 5; **XV** 3-10; **XVI** 21; **XVII** 15-18  
 sites visited by East Grinstead field group **IV** 27-28  
 slag *see also* cinder  
     bloomery  
         use in blast furnaces **V** 10  
         identification of **III** 9  
     on Roman road **XVII** 9  
     table of running temperatures **IV** 7  
     road, Surrey **IV** 30  
 Slaugham (West Sussex)  
     Slaugham Furnace/Forge **V** 16; **X** 28  
 Slaugham field group **V** 15  
 Slinfold (West Sussex) **X** 28  
 Sloane manuscripts **XVI** 17, 18  
 Slonk Hill *see under* Shoreham  
 smelting process **IV** 4-5  
 Smith, Margaret **XVII** 14  
 Smith, Thomas **XVII** 14  
 Smithfield Shaw Bloomery *see under* Mayfield  
 Smythe, J. A. **XIV** 3, 4  
 Snape (Scrag Oak) Furnace *see under* Wadhurst  
 Snape Mine *see under* Wadhurst  
 Snatchell, John **XVI** 10  
 Sobrys, Guillam **XVI** 6  
 Socknersh Furnace *see under* Brightling  
 Sorcy (France) **XVI** 6; **XVII** 3  
 Southborough (Kent)  
     Brokes Wood pond **III** 10  
 Spaulines bloomery *see under* Buxted  
 Speldhurst (Kent) **XVII** 17  
 Stainbridge, G. **IV** 29  
 Standard Hill Farm *see under* Ninfield  
 ‘Standford Furnace and Forge’ *see under* Bramshott  
 Stedham (West Sussex)  
     Inholmes Copse Furnace **VII** 13  
 steel  
     blister **XIV** 11  
     German **XIV** 11  
 Steel Forge *see under* Warbleton  
 Steel Forge, Pippingford *see under* Hartfield  
 Stiele, John **XVI** 3  
 Stomlett (Stumblett, Stublett) Furnace *see under* Maresfield  
 Stone Furnace *see under* East Grinstead  
 Stonelands (Withyham) Furnace *see under* Withyham  
 Straker, E. **XV** 2, 8  
     list of recorded sites, **I** 13-17  
     memories of **III** 2; **VI** 10  
 Stream Furnace and Forge *see under* Chiddingly  
 Streeten, A. D. F. **XV** 16  
 Streeters Farm Bloomery *see under* Maresfield  
 Strickedridge Gill Bloomery *see under* Hartfield  
 Strudgate Furnace *see under* Ardingly  
 Stumblett (Stublett, Stoznlett) Furnace *see under* Maresfield  
 Surney Hatch *see under* Fernhurst  
 Sussex Ironworks, hist. and arch. notes 1847 **X** 2-21  
 Symar, Lambert **XVI** 9  
  
 Tamplier, James **XVI** 5  
 Tankards Croft bloomery *see under* Buxted  
 Tankerye, Roger **XVI** 5  
 Teale, William **XVI** 3  
 Tebbutt, C.F. **II** 7, 11, 12; **IV** 22; **V** 11; **VI** 8; **VIII** 45, 46; **IX** 21,  
     22, 23, 25, 27; **XI** 5, 9, 14; **XII** 3, 14; **XIII** 2, 6; **XIV** 2, 5, 6,  
     8; **XV** 2, 31; **XVI** 14, 20; **XVII** 15  
 Tebbutt, O.M. **XVI** 20  
 Tenchley (Tinsley) Forge *see under* Crawley

Thundersfield Castle *see under* Horley  
 Thursley (Surrey)  
     Horsebane Hammer Forge **IX** 5  
     Thursley Furnace and Forges **IX** 5  
 Ticehurst (East Sussex) **II** 4, 5; **VIII** 38; **X** 28  
     aliens in **IV** 12  
     Bardown **I** 2, 4, 12; **II** 4, 5, 12; **IV** 5, 7, 24  
     East Lynden Furnace **II** 6; **VIII** 38  
     Holbeanwood excavations **I** 4: **II** 4, 12  
     Wedds Valley **VIII** 38  
 Tickerage Furnace and Forge *see under* Framfield  
 Tidy, Richard **XIII** 25  
 Tilgate Furnace *see under* Crawley  
 Tilehurst Farm *see under* Dorking  
 Tilsmore Wood Bloomery *see under* Heathfield  
 Tinkers Wood Bloomery *see under* Maresfield  
 Tinsley Forge *see under* Crawley  
 tithe apportionment schedules **III** 8-9  
 Tollett, Jerman **XVI** 6  
 Tollslie Forge *see under* Frant  
 Tollslie Furnace *see under* Frant  
 Tonbridge (Kent) **VIII** 28; **IX** 8, 9; **XVII** 17  
     Postern Forge **XVII** 17  
     Rats Castle Forge **IX** 9  
     Vauxhall Furnace **IX** 8  
 Topley, W **I** 10  
 Torshey, Gillam **XVI** 7  
 Totease *see under* Buxted  
 Titayn, Jeffrey **XVI** 7  
 Toulett, Philip **XVI** 5  
 Tournewys, Martyn **XVI** 8  
 Towes, R. **XI** 15  
 Trajan, emperor **XVI** 15  
 Trotton (West Sussex)  
     aliens in **IV** 12  
 Tudeley bloomery *see under* Capel  
 Tugmore Shaw *see under* Hartfield  
 Turke, John **XVI** 6  
 Turners Green bloomery *see under* Warbleton  
 Turners Hill (West Sussex)  
     Fen Place **XIV** 14  
     Worth Forest Furnace **VII** 18  
 Turnyshe, Robert **XVI** 10  
 Turrell, Francis **XVI** 8  
 Twineham (West Sussex) **X** 28  
 Tylecote, R.F. **III** 9; **IV** 4; **XIV** 4  
 Tyler, Anthony **XVI** 7  
 Tyler, James **XVI** 9  
 Tyler, Nicholas **XVI** 5  
 Tyler, Robert **XVI** 7  
 Tyler, Simon **XVI** 6  
 Tyller, Reme **XVI** 2, 5  
 Tyrwhitt, Robert **XVI** 6  
  
 Uddys, Nicholas **XVI** 6  
 Upper Parrock bloomeries *see under* Hartfield  
 Upper Stonehurst bloomeries *see under* Lingfield  
  
 Valion, John **XVI** 3  
 Valley, Robert **XVI** 3  
*Valor Ecclesiasticus* **VII** 7  
 Vasell, Woden **XVI** 8  
 Vauroux, le (France) **XVI** 8; **XVII** 3  
 Vauxhall Furnace *see under* Tonbridge  
 Velett, Gilham **XVI** 7  
 Verdley Wood Furnace *see under* Fernhurst  
 Vere, John **XVI** 8  
 Vernes, John **XVI** 8  
 Verredge Forge *see under* Frant  
 Vespasian, emperor **XVI** 14  
 Vigott, John **XVI** 5

Vinton, John XVI 6  
 Vylean, John XVI 11  
 Vyllan, Peter XVI 5  
 Vynten, Peter XVI 5  
  
 Wadhurst (East Sussex) **I** 2, 4; **II** 5, 12; **III** 13; **VIII** 10, 33, 34, 35, 36, 44; **X** 28  
     aliens in **IV** 12, 13  
     Dooze's Farm bloomery **II** 5  
     Frankham **XIII** 9  
     Mousehall **VIII** 10  
     Sandyden Gill bloomery **VII** 10  
     Scrag Oak (Snape) Furnace **VIII** 36  
     Snape Mine **VIII** 44  
     Wallcrouch **I** 4  
 Wakehurst *see under* Ardingly  
 Waldron (East Sussex) **X** 29  
     bloomeries **III** 12; **VIII** 3  
     Waldron Furnace **XV** 10; **XVI** 13  
 Walesbeech bloomery **II** 6; **VI** 18; **VII** 1-2  
 Wallcrouch *see under* Wadhurst  
 Walnut Tree Field bloomery *see under* Rotherfield  
 Walys, James XVI 11  
 Warbleton (East Sussex) **VII** 23, 24; **IX** 8, 9; **X** 29; **XIV** 8  
     Markly (Rushlake Green) Furnace **VII** 24  
     Rushlake Green bloomery **XIV** 5  
     Steel Forge **VIII** 5; **IX** 9  
     Tuners Green bloomery **VI** 8  
     Warbleton Priory Furnace and Forge **VII** 25  
     Woodmans Furnace or Forge **IX** 8  
 Warnham (West Sussex) **V** 20  
 Warnham Furnace *see under* Horsham  
 Warren Furnace *see under* Worth  
 Wassell Forge *see under* Ebernoe  
 water-power  
     sites visited by WIRG **VI** 23-31; **VII** 13-27; **VIII** 12-44; **IX** 5-18; **XI** 6-8; **XIV** 5; **XV** 10; **XVI** 20; **XVII** 17  
 wealden iron industry  
     bibliographies **III** 20-23  
     chemistry of **IV** 3-10  
 Wealden Iron Research Group  
     aims and objectives **I** 19  
     Hon Secretary's Report 1972 **III** 16-18  
     list of members at 31/12/71 **III** 24  
     relationship with other bodies **I** 26  
     organisation **I** 20  
 Weale, James **XVI** 11  
 Weavers Down *see under* Greatham  
 Weekes, Richard XVI 5  
 Wedds Farm/Valley *see under* Ticehurst  
 Welley, John XVI 10  
 West Chiltington (West Sussex) **I** 10  
     Broadford Bridge **I** 10  
     Gatewick Farm **I** 10  
     Gay Street **I** 10, 11  
     Willets Farm **I** 10  
 West End Furnace *see under* Chiddingfold  
 West Hoathly (West Sussex) **VIII** 15; **X** 29; **XI** 6  
     Chittingly Furnace **XI** 6  
     Gravetye Furnace **IV** 27; **VIII** 15; **XIV** 16-22; **XVI** 13; **XVII** 6  
 West Sussex Field Group **IV** 29  
 western Weald – geology **I** 10-11  
 Westfield (East Sussex) **X** 29  
     Westfield (Crowham) Forge **VIII** 6; **XVI** 12, 13  
 Westrum, Mr XVI 13  
 Westwell (Kent) **VI** 3  
     Hammer Forge **VI** 4  
 Weyo, John XVI 10  
 Whillets Bridge bloomery *see under* East Grinstead  
 White, Peter XVI 4  
 White, W.P. **IX** 18

Wick Wood *see under* Hartfield  
Wicks Coppice *see under* Crowhurst  
Wilderwick *see under* Lingfield  
Willets Farm *see under* West Chiltington  
Willis XVI 13  
Willmott, P. XI 29  
Winbolt, S.E . V 11  
Wire Mill (Woodcock Hammer) Forge *see under* Felbridge  
Wisborough Green (West Sussex) VII 17; X 29  
    Cinderberry Field IX 24  
    Pallingham Furnace VIII 3; VII 17  
Witherenden *see under* Mayfield  
Withyham (East Sussex) I 4; II 11; X 29; XI 9; XV 4  
    Bingles Farm bloomery VII 12; XV 4  
    Crowborough (Grubsbars) Forge VI 29; IX 7  
    Crowborough Warren (Withyham) Furnace VI 28; VIII 45; XI 9:  
        XII 2  
    Withyham Forge VIII 23  
Witley, Surrey)  
    Witley Park Furnace XIII 3  
Wivelsfield (East Sussex) V 12; VI 5  
Woodcock Hammer Forge *see under* Felbridge  
Woodman's Furnace and (?)Forge *see under* Warbleton  
Woolbridge water-powered bloomery *see under* Mayfield  
Woolwich (Kent) XIV 12, 14-20  
Wotton (Surrey)  
    Friday Street VIII 44.  
Worssam, B . I 11; IV 26; V 20  
Worth (West Sussex) VIII 14, 15; X 26; XVII 19  
    Crawley Down XIV 20  
    Rowfant XIV 21  
    Rowfant Forge VIII 5  
    Warren (Hedgecourt) Furnace VIII 15; XIV 11-24; XVI 13; XVII  
        6, 19  
Worth Forest Furnace *see under* Turners Hill  
Wrotham (Kent) VI 3, 5  
Wybarn, master XVI 6